

AN AMERICAN NATIONAL STANDARD

Gages and Gaging for Unified Inch Screw Threads

ANSI/ASME B1.2-1983

(REVISION OF ANSI B1.2-1974)

SPONSORED AND PUBLISHED BY

THE AMERICAN SOCIETY OF MECHANICAL ENGINEERS

United Engineering Center 345 East 47th Street New York, N. Y. 10017

CONTENTS

Foreword		iii
Standards Committee Roster		v
1 Introduction		1
1.1 References		1
1.2 Classification		1
1.3 Federal Government Use		1
2 Basic Principles		1
2.1 Accuracy in Gaging		1
2.2 Limitations of Gaging		1
2.3 Determining Size of Gages		10
2.4 Standard Temperature		10
3 General Practice		10
3.1 General Design		10
3.2 Types of Gages		10
3.3 Interpretation of Tolerances		10
3.4 Direction of Tolerances on Gages		10
3.5 Standard Thread Gage Tolerances		11
3.6 Tolerance on Lead		11
3.7 Tolerances on Half-Angle		11
3.8 Check of Effect of Lead and Flank Angle Variations on Product Thread		11
3.9 Calibration Requirements and Standards		11
4 Types of Gages for Product Internal Thread		11
4.1 GO Working Thread Plug Gages		11
4.2 NOT GO (HI) Thread Plug Gages		13
4.3 Thread Snap Gages — GO Segments or Rolls		14
4.4 Thread Snap Gages — NOT GO (HI) Segments or Rolls		20
4.5 Thread Snap Gages — Minimum Material: Pitch Diameter Cone and Vee		20
4.6 Thread Snap Gages — Minimum Material: Thread Groove Diameter Type		23
4.7 Thread-Setting Solid Ring Gages		24
4.8 Plain Plug, Snap, and Indicating Gages to Check Minor Diameter of Internal Thread		24
4.9 Snap and Indicating Gages to Check Major Diameter of Internal Thread		28
4.10 Functional Indicating Thread Gages for Internal Thread		28
4.11 Minimum-Material Indicating Thread Gages for Internal Thread		33
4.12 Indicating Runout Thread Gage for Internal Thread		33
4.13 Differential Gaging		37

4.14	Pitch Micrometers	39
4.15	Thread-Measuring Balls	39
4.16	Optical Comparator and Toolmaker's Microscope	39
4.17	Profile Tracing Instrument	40
4.18	Surface Roughness Equipment	40
4.19	Roundness Equipment	40
4.20	Miscellaneous Gages and Gaging Equipment	40
5	Types of Gages for Product External Thread	40
5.1	GO Working Thread Ring Gages	40
5.2	NOT GO (LO) Thread Ring Gages	128
5.3	Thread Snap Gages — GO Segments or Rolls	129
5.4	Thread Snap Gages — NOT GO (LO) Segments or Rolls	131
5.5	Thread Snap Gages — Cone and Vee	133
5.6	Thread Snap Gages — Minimum Material: Thread Groove Diameter Type	133
5.7	Plain Ring and Snap Gages to Check Major Diameter of Product External Threads	133
5.8	Snap Gages for Minor Diameter of Product External Threads	135
5.9	Functional Indicating Thread Gages for External Thread	135
5.10	Minimum-Material Indicating Thread Gages for External Thread	139
5.11	Indicating Runout Gage for External Threads	139
5.12	Differential Gaging	139
5.13	W Tolerance Thread-Setting Plug Gages	143
5.14	Plain Check Plug Gages for Thread Ring Gages	148
5.15	Indicating Plain Diameter Gages — Major Diameter of Product External Threads	148
5.16	Indicating Gages to Check Minor Diameter of External Thread	148
5.17	Thread Micrometers	159
5.18	Thread-Measuring Wires	159
5.19	Optical Comparator and Toolmaker's Microscope	159
5.20	Profile Tracing Instrument	160
5.21	Electromechanical Lead Tester	160
5.22	Helical Path Attachment Used With GO Type Thread Indicating Gage	160
5.23	Helical Path Analyzer	160
5.24	Surface Roughness Equipment	161
5.25	Roundness Equipment	161
5.26	Miscellaneous Gages and Gaging Equipment	161
Figures		
1	Maximum-Material GO Functional Limit	12
2	Partial End Threads and Chip Grooves	14
3	NOT GO (HI) Functional Diameter Limit	16
4	Thread Snap Gages — Maximum-Material GO Functional Limit	19
5	Thread Snap Gages — NOT GO (HI) Functional Diameter Limit	21
6	Thread Snap Gages — Minimum-Material Pitch Diameter Limit — Cone and Vee	22
7	Thread Snap Gages — Minimum-Material Thread Groove Diameter Limit	23
8	Thread Form of Solid Thread-Setting Ring Gages	26
9	Minor Diameter Limit — Cylindrical Plug Gages	27
10	Indicating Plain Diameter Gages — Max.-Min. Minor Diameter Limit and Size	29
11	Snap and Indicating Diameter Gages — Max.-Min. Major Diameter Limit and Size	30

12	Indicating Thread Gages — Maximum-Material GO Functional Limit and Size	31
13	Indicating Thread Gages — Minimum-Material Pitch Diameter Limit and Size — Cone and Vee	34
14	Indicating Thread Gages — Minimum-Material Pitch Diameter Limit and Size — Ball and Radius	35
15	Indicating Thread Gages — Diameter Runout — Minor to Pitch	36
16	Indicating Thread Gages — Differential Gaging	38
17	Inside Micrometer, Caliper Type	39
18	Maximum-Material GO Functional Limit	127
19	NOT GO (LO) Functional Diameter Limit	129
20	Thread Snap Gages — Maximum-Material GO Functional Limit	130
21	Thread Snap Gages — NOT GO (LO) Functional Diameter Limit	132
22	Thread Snap Gages — Minimum-Material Pitch Diameter Limit — Cone and Vee	134
23	Thread Snap Gages — Minimum-Material Thread Groove Diameter Limit	135
24	Major Diameter Limit	136
25	Minor Diameter Limit Snap Type	137
26	Indicating Thread Gages — Maximum-Material GO Functional Diameter Limit and Size	138
27	Indicating Thread Gages — Minimum-Material Pitch Diameter Limit and Size — Cone and Vee	140
28	Indicating Thread Gages — Minimum-Material Thread Groove Diameter Limit and Size	141
29	Indicating Thread Gages — Diameter Runout — Major to Pitch	142
30	Indicating Thread Gages — Differential Gaging	144
31	Thread Form of Truncated Thread-Setting Plug Gages	146
32	Thread Form of Full-Form Thread-Setting Plug Gages	147
33	Indicating Plain Diameter Gage — Max.-Min. Major Diameter Limit and Size	149
34	Indicating Diameter Gages — Max.-Min. Minor Diameter Limit and Size	150
35	Indicating Gages — Helical Path Attachment Used With GO Type Indicating Gage	160

Tables

1	Screw Thread Gages and Measuring Equipment for External Product Thread Characteristics	2
2	Screw Thread Gages and Measuring Equipment for Internal Product Thread Characteristics	6
3	Recommended Widths for Chip Grooves	13
4	Specifications and Format for Tables 10 and 11 — Limits of Size of Threaded and Plain Gages for Unified External and Internal Threads	15
5	Specifications and Format for Tables 10 and 11 — Limits of Size of Thread- Setting Gages for Unified Thread Working Gages	17
6	X Gage Tolerances for Thread Gages	18
7	W Gage Tolerances for Thread Gages	25
8	Gage Tolerances for Plain Cylindrical Gages	28
9	Constants for Computing Thread Gage Dimensions	32
10	Gages for Standard Thread Series, Classes 1A, 2A, 3A, 1B, 2B, and 3B Unified Screw Threads — Limits of Size	41
11	Setting Gages for Standard Thread Series, Classes 1A, 2A, 3A, 1B, 2B, and 3B Unified Screw Threads — Limits of Size	83
12	Calibration Requirements and Standards for X Tolerance Thread Gages, Indicating Gages, Plain Gages, and Measuring Equipment for External Product Threads	151

13	Calibration Requirements and Standards for X Tolerance Thread Gages, Indicating Gages, Plain Gages, and Measuring Equipment for Internal Product Threads	155
14	Calibration Requirements for Thread- and Plain-Setting Gages	159

Appendices

A Calibration and Inspection of Limit Gages, Snap Gages, Indicating Gages, and Measuring Instruments

A1	General	163
A2	Thread Plug Gage Calibration	163
A3	Thread Ring Gage Inspection	164
A4	Plain Plug Gage Calibration	167
A5	Plain Ring Gage Calibration	168
A6	Plain Snap Gages	168
A7	Rolls With Zero Lead Thread Form Used on Snap and Indicating Gages	168
A8	Inspecting Peripheral Contacting Segments Used on External Product Thread	168
A9	Inspection of Thread Contact Segments Used on Internal Product Thread	170
A10	Check for Magnification Discrepancies Due to Indicating System Linkage	170
A11	Calibration of Dial and Electronic Indicators	170
A12	Assessment of Surface Quality	171

B Metrology of 60 deg. Screw Threads

B1	Wire Method of Measurement of Pitch Diameter (Thread Groove Diameter)	173
B2	Size of Wires	173
B3	Methods of Measuring Wires Considering the Effect of Deformation	173
B4	Methods of Measurement Using Wires	176
B5	Standard Specification for Wires and Standard Practice in Measurement of Wires of 60 deg. Threads	176
B6	General Formula for Measurement of Pitch Diameter	177
B7	Simplified Formula for Pitch Diameter	177
B8	Setting Measuring Instruments With Variable Measuring Force	178
B9	Thread Balls	178
B10	Internal Pitch Diameter Measurement	179

Figure

B1	A Three-Wire Method of Measuring Pitch (Thread Groove) Diameter of Thread Plug Gages	174
----	--	-----

Tables

A1	Minimum Magnification	164
A2	60 deg. Included Thread Angle	165
A3	Lengths of AGD Taperlock and Trilock Thread Plug Gage Blanks Selected From ANSI B47.1	166
A4	Lengths of AGD Thread Ring Gage Blanks and Total Thread Lengths of Standard Truncated-Setting Plug Gage Blanks Selected from ANSI B47.1	169
B1	Thread-Measuring Wires for 60 deg. Screw Threads	175
B2	Measuring Force for Over-Wire Measurements of External Pitch Diameter and Wire Calibration, and Cylindrical Diameter for Wire Calibration	176
B3	Measuring Force Over Balls for Internal Pitch Diameter Measurement and Ball Calibration	179